



Quantum SuperLoader 3 V93 Release Notes

Product	SuperLoader 3 V93
Date	December 2016

Contents

Purpose of This Release	1
New Features and Enhancements	2
Supported Drives	2
Cautions and Warnings	3
Known Issues	3
Documentation	5
Contacting Quantum	5

Purpose of This Release

This document describes the changes for the V93 release of SuperLoader 3 Firmware.

Visit <http://www.quantum.com/serviceandsupport/softwareanddocumentationdownloads/superloader3/index.aspx> for additional information about the SuperLoader 3 and previous releases.

New Features and Enhancements

This release provides a fix for an issue in which the SL3 failed to support Sequential mode when using IBM LTO tape drives.

Supported Drives

The V93 release of SuperLoader 3 Firmware supports the following drives:

- LTO7 (all versions, heights, and interfaces)
- LTO6 (all versions, heights, and interfaces)
- LTO5 (all versions, heights, and interfaces)
- LTO4 (all versions, heights, and interfaces)
- LTO3 (all versions, heights, and interfaces)

Unsupported Drives

The V93 release of SuperLoader 3 Firmware does not support the following drives:

- LTO2 (all versions, heights, and interfaces)
- SDLT600 (all versions, heights, & interfaces)
- SDLT320 (all versions, heights, & interfaces)
- SDLT220 (all versions, heights, & interfaces)
- DLTS4 NFC (all versions, heights, & interfaces)
- DLTV4 (all versions, heights, & interfaces)
- VS160 (all versions, heights, & interfaces)
- VS80 (all versions, heights, & interfaces)

Cautions and Warnings

System

The following are cautions and warnings for the system:

- It is necessary that the unit be properly mounted in a rack or sitting flat on a hard surface with support under the entire unit.
- When power cycling the unit, please wait 10 seconds before powering it back on.
- Windows 2008 *does not* support LTO-7 tape drives.

Known Issues

SuperLoader 3 has the following known issues.

PCR Number	ATLca Number	Description	Workaround
17902		When changing the barcode scanner configuration on the OCP, the user is not immediately notified that a power cycle is required.	The user must hit the ESC key to get to the top level before the message is displayed. (However, until the user power cycles, active operations from the OCP are not allowed.)
17957		In the Remote Management Unit, when entering information in Configurations > Security , under the heading " Client Authorization Control ," be sure that any IP address values that are entered contain valid characters.	If not, the invalid characters will simply be ignored, and the remaining valid characters will be taken as the IP address. There will be no warning given to the user. This may or may not produce intended results for the user.
18216		With an existing static site local IPv6 address set, when setting the IPv6 address to a new site local address that is the same as the current router-assigned site local address the new address is rejected without giving the user an error message that the address was rejected. Also, when the new address is rejected, the prior old static site local address is removed from the "Current Network Parameters" section on the Configuration page and is no longer functional.	To restore this site local connectivity, either clear the IPv6 address from the RMU field and submit or enter a non-router-assigned address value.

PCR Number	ATLca Number	Description	Workaround
18376		When using Red Hat 5.1, Firefox 1.5.0.12 or other browsers may not be able to connect to the Superloader 3 system.	This is caused by the operating system itself directing network traffic to a virtual network interface. The failure is intermittent. RH 5.0, RH4.0 and other operating systems work fine.
17874		When using Windows Server 2008, on the Configurations/Security page under "User Administration," if a user of type "Operator" is created, there will be problems when this user tries to log back to the system using Internet Explorer 7. The problem only occurs with this combination of browser and operating system. This occurs when the user opens a new browser. The user is presented with a login screen, and the login attempt will fail. Note: Windows 2008 does not support LTO-7 tape drives.	To workaround this, cancel the login window, and select a page that does have operator access, such as the Command page. The login will succeed.
17894		When using a browser on Windows Server 2008, occasionally HTML text appears on the Web page. This text appears in the Status pane and on the main pages, usually during the auto-refresh.	Refreshing the browser remedies the issue.
40856		A Microsoft feature can keep a user from seeing the complete file path when updating drive or loader firmware over the On-board Remote Management interface. This can occur with Internet Explorer 7.0 or higher. This problem will display the text "fakepath" in the file path for the firmware being downloaded and installed.	To see the full file path, enter the Internet Explorer Toolbar location: 1 Tools > Internet Options > Security > Custom Level > Include local directory path when uploading files to a server. 2 Click the Enable button. 3 Click OK , then Apply , and finally OK to set this new setting. 4 You should be able to see the full path name on the RMU for the firmware file being downloaded.
58922		Network security scanners using an invasive telnet scan may cause the Operator Control Panel (OCP), the Remote Management connection, and the host interfaces to lock up.	Power cycle the SuperLoader3 to recover from the lock-up. Exclude the SL3 IP address from future scans.

Documentation

The following documents are currently available for the Quantum SuperLoader 3 on www.quantum.com (<http://www.quantum.com/serviceandsupport/softwareanddocumentationdownloads/superloader3/index.aspx>):

Document Number	Document Title
81-81317-xx	SuperLoader 3 User's Guide
81-81313-xx	SuperLoader 3 Quick Start Guide

Contacting Quantum

More information about this product is available on the Service and Support Website at <http://www.quantum.com/serviceandsupport/index.aspx>. The Service and Support Website contains a collection of information, including answers to frequently asked questions (FAQs). You can also access software, firmware, and drivers through this site.

For further assistance, or if training is desired, contact Quantum:

Region	Support Contact
North America	1-800-284-5101 (toll free) +1-720-249-5700
EMEA	+800-7826-8888 (toll free) +49 6131 324 185
Asia Pacific	+800-7826-8887 (toll free) +603-7953-3010

For worldwide support:

<http://www.quantum.com/serviceandsupport/index.aspx>