

Aladdin 1.12.0.0 build 151030.1351

Software Release Notes

1. Release Features and bug fixing

This is an upgrade version with bug fixing the critical issue from field about Advanced Formatting does not work as expected. Issue found on release **1.11.0.0**.

Detail history of changes and bug fixed are listed on next three sections following here below.

2. Supported Product List – *page 2*.

2.1. Standard build-in product list – *page 2 – 4*.

2.2. New product and maintenance release support – *page 5*.

2.3. Obsolete Products and non-support model List – *page 5 – 7*.

3. Software defects closed – *page 8*.

2. Supported Product List

Currently Aladdin distribution support all Datalogic ADC Hand Held products within the exception of those appear in the obsolete list.

The Standard build-in list shows all products and SW releases explicitly present in the installation package of current version.

Regular web updates of supporting new SW release are provided and can be checked with the Aladdin embedded functionality search for updates.

2.1. Standard build-in Products List

#	Standard build-in Products List
1	2D Decoded Scan Engine_610057404
2	BC2030-BT-BASE-CHARGER_610049811
3	BC2030-BT-BASE-CHARGER_610049817
4	BC2030-STAR433-BASE-CHARGER_610049711
5	BC2030-STAR433-BASE-CHARGER_610049717
6	BC2030-STAR433-BASE-CHARGER_610049718
7	BC40x0-BASE-CHARGER_610018705
8	BC40x0-BASE-CHARGER_R96-9577
9	BC40x0-BT-BASE-CHARGER_610002601
10	BC40x0-BT-BASE-CHARGER_610002607
11	BC40x0-BT-BASE-CHARGER_610018904
12	BC40x0-BT-BASE-CHARGER_610018914
13	BC70x0-BASE-CHARGER_610019902
14	BC70x0-BASE-CHARGER_R96-9468
15	BC90x0-BASE-CHARGER_610037508
16	BC90x0-BT-BASE-CHARGER_610037606
17	BC9x80-BASE-CHARGER_610054702
18	BC9x80-BASE-CHARGER_610054707
19	BC9x80-BT-BASE-CHARGER_610054901
20	CO5330_610049304
21	CO5330_610049315
22	GFS4150-9_R96-9584
23	GFS4170_R96-9582
24	Gryphon-BT4100_610018804
25	Gryphon-BT4100_R96-9469
26	Gryphon-D41xx_610018502
27	Gryphon-D41xx_R96-9391
28	Gryphon-D43xx_610019602

#	Standard build-in Products List
29	Gryphon-D43xx_R96-9400
30	Gryphon-GBT4400_610001715
31	Gryphon-GBT4400_610001723
32	Gryphon-GD44xx_610001021
33	Gryphon-GFE4490_610023802
34	Gryphon-GFS4450_610015505
35	Gryphon-GFS4450_610043900
36	Gryphon-GFS4470_610015505
37	Gryphon-GM4400_610005511
38	Gryphon-GPS4421_610080201
39	Gryphon-GPS4490_610040703
40	Gryphon-M4100_610018605
41	Gryphon-M4100_R96-9578
42	HERON D110_3.0.0.02
43	HERON D130_3.0.0.02
44	Heron-HD3130_610023416
45	Heron-HD3430_610072818
46	Heron-HD3430_610072819
47	OM-BC-80X0_3.0.0.00
48	OM-BC-80X0_610001601
49	OM-BC8030-BT_610003600
50	OM-QUICKSCAN M2110_1.0.1.00
51	OM-QUICKSCAN M2110_610001400
52	OM-QUICKSCAN M2130_1.0.3.00
53	OM-QUICKSCAN M2130_610001500
54	POWERSCAN BT8300-DK_610003801
55	POWERSCAN BT8300_610003701
56	Powerscan BT9500-DPM_610040006
57	Powerscan BT9500_610025805
58	POWERSCAN D8330_2.0.0.00
59	POWERSCAN D8530_1.05.000
60	Powerscan D9530-DPM_610032702
61	Powerscan D9530_610025404
62	POWERSCAN M8300-DK_3.0.0.02
63	POWERSCAN M8300-DK_R96-9590
64	POWERSCAN M8300_2.0.1.00
65	POWERSCAN M8500_1.05.000
66	Powerscan M9500-DPM_610040314
67	Powerscan M9500_610025510

#	Standard build-in Products List
68	POWERSCAN-M8500_1.05.000
69	Powerscan-PBT-71x0_610019802
70	Powerscan-PBT-71x0_R96-9467
71	Powerscan-PD71x0_610019702
72	Powerscan-PD71x0_R96-9398
73	QUICKSCAN M2130_1.0.0.02
74	QuickScan-i-QD2131_610056822
75	QuickScan-i-QD21x0_610018402
76	QuickScan-i-QD21x0_R96-9399
77	QuickScan-QBT2400_610041105
78	QuickScan-QD2430-E_610058000
79	QuickScan-QD2430_610028608
80	QuickScan-QM2430_610041205
81	QuickScanLite-i-QW2120-E_610042911
82	QuickScanLite-i-QW2120_610008111
83	QuickScanLite-i-QW2120_610043508
84	QuickScanLite-i-QW2121_610043503
85	QuickScanLite-i-QW2170-E_610043011
86	QuickScanLite-i-QW2170_610008311
87	QuickScanLite-i-QW2170_610043708
88	QuickScanLite-i-QW2171_610043703
89	TouchLite-i-TD1120_610013114
90	TouchLite-i-TD1170_610013314
91	TouchPro-i-TD1130_610013514

2.2. New product and maintenance release support

#	Obsolete Product Model and Release non-support
1	Gryphon-GBT4400_610001723
2	BC40x0-BT-BASE-CHARGER_610018914
3	CO5330_610049315
4	BC2030-BT-BASE-CHARGER_610049817
5	BC2030-STAR433-BASE-CHARGER_610049717
6	QuickScan-i-QD2131_610056822
7	BC2030-BT-BASE-CHARGER_610049817
8	BC2030-STAR433-BASE-CHARGER_610049718
9	Heron-HD3130_610023416
10	Heron-HD3430_610072819
11	Gryphon-GPS4421_610080201
12	2D Decoded Scan Engine_610057404

2.3. Obsolete Products and non-support model List

Obsolete Products model List will no longer support by Aladdin application in this version, but still support in version **1.7.0.0** and **1.6.2.0**.

1. C-30X0
2. C-8000
3. CATCHER_D531-DLL2220
4. DIAMOND_D531-DLL2020
5. DRAGON D131
6. DRAGON M101
7. FIRESCAN D111
8. FIRESCAN D111 / D131
9. GRYPHON D130 LR
10. GRYPHON D130 STD
11. GRYPHON D230 STD
12. GRYPHON D412PLUS / D432PLUS
13. GRYPHON_M130/M230 STD 433MHz
14. HERON D130 MASK
15. HERON-G D130 MASK
16. OM-30X0
17. OM-DRAGON
18. OM-GRYPHON
19. STAR MODEM
20. TOUCH LIGHT
21. TOUCH MASK

22. TOUCH

23. PM 8500

Following that list XML configuration library will be removed out from Aladdin application

#	Obsolete Product Model and Release non-support
1	BC40x0-BASE-CHARGER_R96-9263
2	BC40x0-BASE-CHARGER_R96-9472
3	BC40x0-BT-BASE-CHARGER_610002601
4	BC40x0-BT-BASE-CHARGER_R96-9277
5	BC40x0-BT-BASE-CHARGER_R96-9470
6	BC70x0-BASE-CHARGER_R96-9283
7	C-30X0_1.0.0-03_b03
8	C-8000_2.0.0.00
9	CATCHER D531 - DLL2220_1.1.0.001
10	DIAMOND D531 - DLL2020_1.1.0.001
11	DRAGON D131 D SH3886_1.0.1
12	DRAGON D131_1.0.0-03_b06
13	DRAGON M101_3.1.4.00
14	DRAGON M131_1.1.0-00_b00
15	FIRESCAN D111_3.0.0.02
16	FIRESCAN D131_3.0.0.02
17	GRYPHON D130 LR_1.0.1.00A
18	GRYPHON D130 STD_1.0.1.00A
19	GRYPHON D230 STD_1.0.1.00A
20	GRYPHON D412PLUS_1.03.00
21	GRYPHON D412PLUS_1.04.00
22	GRYPHON D432PLUS_1.03.00
23	GRYPHON D432PLUS_1.04.00
24	GRYPHON M130 STD 433MHz_1.0.1.00A
25	GRYPHON M230 STD 433MHz_1.0.1.00A
26	Gryphon-BT4100_R96-9276
27	Gryphon-D41xx_R96-9257
28	Gryphon-D43xx_R96-9275
29	Gryphon-GBT4400_610001702
30	Gryphon-GD44xx_610001000
31	Gryphon-GD44xx_610001001
32	Gryphon-GD44xx_610001007
33	Gryphon-M4100_R96-9262
34	Gryphon-M4100_R96-9471
35	HERON D130 MASK_1.0.0.00

#	Obsolete Product Model and Release non-support
36	HERON D130_2.1.0.00
37	HERON-G D130 MASK_1.0.0.00
38	OM-30X0_1.0.1-00_b00
39	OM-30X0_1.1.0-00_b00
40	OM-BC-80X0_2.0.0.00
41	OM-DRAGON_3.1.3.00
42	OM-GRYPHON_5.00.03
43	OM-QUICKSCAN M2130 SS4069_1.00
44	OM-QUICKSCAN M2130_1.0.1.00
45	POWERSCAN D8530_1.02.000
46	POWERSCAN D8530_1.04.000
47	POWERSCAN M8300 SS3948_1.0.0
48	POWERSCAN M8300_2.0.0.00
49	POWERSCAN M8500_1.03.000
50	POWERSCAN M8500_1.04.000
51	Powerscan-PBT-71x0_R96-9282
52	Powerscan-PD71x0_R96-9281
53	QuickScan-i-QD21x0_R96-9252
54	QuickScan-i-QD21x0_R96-9399
55	STAR-MODEM_2.01
56	STAR-MODEM_2.10
57	TOUCH LIGHT_3.0.0.02
58	TOUCH LIGHT_3.0.1.00
59	TOUCH MASK_1.0.0.00
60	TOUCH_2.1.0.00
61	TOUCH_3.0.0.02
62	Heron-HD3130_610023412
63	Heron-HD3130_610023413
64	Heron-HD3430_610072813

3. Software Defects Closed

3.1. Version 1.12.0.0

#	ID	Description
1	ALDN_CFG_REQUEST_159	[Orion - HHR1D_SWCR_1445] Unable to access Format 1, 2, 3, 4
2	ALDN_CFG_REQUEST_90	[Terminal] "Show Not Printable Chars" should be unchecked by default
3	ALDN_CFG_REQUEST_154	[Splash Screen] Change year of text "Copyright 2000-2014..." to current year
4		Unable to connect to PS8300 in USB COM, "Null" message, REGRESSION, works with 1.7

3.2. Version 1.11.0.0

On this release, we closed about 14 defects and change request for enhancement Aladdin application as below

#	ID	Description
1	ALDN_CFG_REQUEST_99	Filter "Null" errors when clicking on unsupported feature, include notification of "unsupported feature"
2	ALDN_CFG_REQUEST_108	[Aladdin]Can't set RGB pattern for the HH by Aladdin
3	ALDN_CFG_REQUEST_110	[Aladdin][RBG tool] Cannot overwrite file that exists
4	ALDN_CFG_REQUEST_109	[Aladdin][RGB tool] GUI of RGB tool do not friendly
5	ALDN_CFG_SWCR_16	[VESPUCCI_SWCR_634] non-english language dialog box show up in english interface
6	ALDN_CFG_REQUEST_120	[Aladdin] Sometime aladdin form do not close although scanner already completely disconnect to Aladdin.
7	ALDN_CFG_REQUEST_139	Aladdin 1.9 hangs when closing scanner tab
8	ALDN_CFG_REQUEST_147	It takes 1 minute to load jingle audio window, too long
9	ALDN_CFG_REQUEST_146	[Cobalto][XML package] Not yet update RGB feature on XML package of Cobalto
10	ALDN_CFG_REQUEST_144	[Jingle] Cannot setting jingle audio file when use app Jingle of Aladdin.
11	ALDN_CFG_REQUEST_142	Opening and closing audio jingle window enables the jingles
12	ALDN_CFG_REQUEST_138	[RGB tool] Should remove focus when color node is empty
13	ALDN_CFG_REQUEST_102	Cannot download Audio file to scanner (import from DELTA_SWCR_219)
14	ALDN_CFG_REQUEST_148	[Upgrade FW Multiple Scanners] Error on frame 1196 (USB only, the same scanner and fw)